

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 7/15/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole_ID: S03CC_008MH

Test ID: D1032-017002

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S03CC_005MH
0			Water Level	
91.5			Dye Test Visible	@ TF - downspout
91.5			Dye Test Visible	@ TF - toilet
198.3999939	06		Tap Factory Active	From 1203 Woodington
198.3999939			Dye Test Visible	@ TFA - cleanout
198.3999939			End of Survey	
198.3999939			Manhole	S03CC_008MH